
<b>5</b>	Weather Consent Decree Water Testing Form	Page 1 of 1
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/2/2009</u>
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S05KK1003MH	Test ID: <u>D1032-034025</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05KK1006MH
0			Water Level	
156.8999939	10		Tap Factory	FROM 5207
156.8999939			Dye Test Visible	@ TF
156.8999939			End of Survey	TEST COMPLETED